Tiandy

Tiandy Technologies Co., Ltd.

No.8 Haitai Huake Rd2(Huayuan), Binhai Hi-Tech Zone, Tianjin 300384, China Tel: +86-22-58596037　Fax: +86-22-58596177　en.tiandy.com

How to make and import https certification

Description: this document will show you how to make https certification，and import it at camera & PC

Prerequisites: Need you install latest version search config tool at your PC

Section 1 Make a https certification

Step 1 Click Tool > Https certificate

Step 2 Make root certificate

Tiandy Technologies Co., Ltd.

No.8 Haitai Huake Rd2(Huayuan), Binhai Hi-Tech Zone, Tianjin 300384, China Tel: +86-22-58596037 Fax: +86-22-58596177 en.tiandy.com

Note: need to noticed, the certificate ID will be the name of certification

Step 3 Make Equipment certificate

3.1 select the root certification

3.2 Input information, need to noticed the certificate ID must be different from the fist certification's password

And for the ip segment, you need to input camera's segment

Tiandy Technologies Co., Ltd.

No.8 Haitai Huake Rd2(Huayuan), Binhai Hi-Tech Zone, Tianjin 300384, China Tel: +86-22-58596037 Fax: +86-22-58596177 en.tiandy.com

Then the certification is finish

📑 test1.crt	2023/5/5 21:48	安全证书	3 KB
📄 test2.pem	2023/5/5 21:53	PEM 文件	5 KB

Section 2 Import certification to camera and PC

Step 1 Click configuration > Safety management > Certificate management

Step 2 Click import and choose the certification, then import it

Tiandy Technologies Co., Ltd.

No.8 Haitai Huake Rd2(Huayuan), Binhai Hi-Tech Zone, Tianjin 300384, China Tel: +86-22-58596037   Fax: +86-22-58596177   en.tiandy.com

Step 3 Go back to Configuration > Advanced Set > HTTPS page, then choose the certification which you import before

Then device's part is finish

Step 4 install certification at PC

Tiandy

Tiandy Technologies Co., Ltd.

No.8 Haitai Huake Rd2(Huayuan), Binhai Hi-Tech Zone, Tianjin 300384, China Tel: +86-22-58596037 Fax: +86-22-58596177 en.tiandy.com

Then this part is finish

Last step reopen the browser and you can see there is no warning on it